

Company Name: Church Fields (Swindon) Management Company Limited

Inspector Name: Thomas Dellow MTPI AssocRICS

Inspection Date: 25 April 2025

Purpose

This site inspection record is used when undertaking regular site inspections and is solely for the purpose of recording and monitoring the common (communal) parts on behalf of the above company.

What Is Included

The below report comments on the general condition of the interior and exterior communal parts (where applicable) as they were found at the time of this inspection.



Please note: This inspection is carried out visually by the property manager or a competent person instructed by the property manager and should not be used for any other purpose than to comment and record the general state and condition of the common (communal) parts that are inspected during a routine site visit. Where further investigation, testing or remedial work is required, a competent person is instructed by the property manager.



BLOCK MANAGEMENT LTD

PROFESSIONAL PROPERTY MANAGEMENT

| Internal Inspection | Acceptable | Not Acceptable | N/A | Comments | Action |
|--|------------|----------------|-----|--|--------|
| Entrances (Main doors) | ✓ | | | The door to flats 60-70 will be replaced in May 2025 | None |
| Hallway (Communal Lobbies and Stairs) | ✓ | | | | None |
| Lighting (Standard and Emergency Lighting) | ✓ | | | | None |
| Internal Doors (Compartment Doors) | ✓ | | | | None |
| Cupboard Doors (Electrical Cupboard Doors) | ✓ | | | | None |
| Windows (Communal Windows) | ✓ | | | | None |
| Signage (Communal Notices) | ✓ | | | | None |
| Additional Comments | | | | | None |



BLOCK MANAGEMENT LTD

PROFESSIONAL PROPERTY MANAGEMENT

| External Inspection | Acceptable | Not Acceptable | N/A | Comments | Action |
|--|------------|----------------|-----|---|--------|
| Exterior Structure (The Building) | ✓ | | | | None |
| Guttering (Gutters and Fascia) | ✓ | | | | None |
| Roofing (Tiles and Cladding) | ✓ | | | | None |
| Communal Grounds (Gardens and Common Areas) | ✓ | | | | None |
| Bin Store (Waste Disposal Areas) | ✓ | | | Fly-tipped items were noted in the bin store however the bins were accessible and clear of obstruction. | Review |
| Car Park (Vehicle Parking) | ✓ | | | | None |
| Bike Store (Bicycle Areas) | | | ✓ | There is no bike store. | None |
| Additional Comments | | | | | None |

Entrances (Main Doors)



Hallway (Communal Lobbies and Stairs)



Lighting (Standard and Emergency Lights)



Internal Doors (Compartment Doors)

Cupboard Doors (Electrical Cupboard Doors)



Windows (Communal Windows)



Signage (Communal Notices)



Additional Photos

Exterior Structure (The Building)



Guttering (Gutters and Fascia)



Roofing (Tiles and Cladding)



Communal Grounds (Gardens and Common Areas)




Bin Store (Waste Disposal Area)



Car Park (Vehicle Parking)



Bike Store (Bicycle Areas)



Additional Photos

